Edenbridge Town Council - Highway Improvement Plan/Action Plan

HIGHWAY IMPROVEMENT PLAN – Stage 1			ACTION PLAN – Stage 2			
Priority	Location	Problem and suggested remedy	Cost Estimate	Funding	Action/Programme	
				Source	(Who/When)	
1.	Main Road and the junction at Hilders Lane and Hillcrest Road	Traffic incidents and serious accidents mainly due to Speed of traffic exceeding speed limit; (see appendix). Main Road			1.Traffic survey required to establish existing speeds and volume of traffic Further advice needed from KCC Highways as to appropriate intervention	
	Edenbridge Town Council strongly recommends that Kent Highways engage with the Town Council for further information on issues at Main Road and Hilders Lane/Hillcrest Road junction Previous highways interventions	Intervention: - Install traffic speed camera traffic calming measures - Hilders Lane/Hillcrest Road Intervention: - Visibility at junction improvements			appropriate intervention	
	(2016) have been ineffective.	- Traffic calming measures				
2.	B2026 at Mill Hill near Blossoms Park entrance (open space area with a Cricket Club and skate park area)	Traffic and road safety at the entrance to Blossoms Park on the B2026 and general speed of traffic on B2026/Mill Hill. (Also near a change of speed limit 50 to 30 mph as entering Edenbridge.) Intervention: - Install a pedestrian crossing near bus stop and entrance to Blossoms Park - Traffic calming measures - Improved signage			1.Traffic survey required to establish existing speeds and volume of traffic Further advice needed from KCC Highways as to appropriate intervention	
3.	Lingfield Road	To review the speed limit on the section of Lingfield Road from Skeynes Road as it leaves Edenbridge. The derestricted (60 mph) limit is sandwiched between 30 mph at the Edenbridge end of			1.Traffic survey required to establish existing speeds and volume of traffic Further advice needed from KCC Highways as to appropriate intervention	

Edenbridge Town Council - Highway Improvement Plan/Action Plan

		Lingfield Road, and 40 mph at the	
		Haxted end/Surrey boarder.	
		Intervention:	
		 To reduce the speed 	
		 Improved signage 	
		- Review HGV restrictions	
4.	Junction of Mont St Aignan Way and	Safety concerns at this junction with	1.Traffic survey required to establish existing speeds and
	Lingfield Road	incidents at the junction from poor	volume of traffic
		phasing times. Also speed	
		approaching lights.	2.To review the traffic light phasing and other traffic
			calming
		Intervention:	
		- To reduce the speed / traffic	Further advice needed from KCC Highways as to
		calming	appropriate intervention
		 Re-phasing of the lights 	
5.	Station Road near Lidl	Pedestrian safety crossing to new	
		stores.	
		Intervention:	
		 Install a pedestrian crossing 	
6.	Swan Lane	Review speed of traffic	1.Traffic survey required to establish existing speeds and
	233233	·	volume of traffic
			Further advice needed from KCC Highways as to
			appropriate intervention
7.	Crouch House Road (near St Brelades	No pavements on a derestricted	1.Traffic survey required to establish existing speeds and
	Court which is homes to the over	road (60 mph).	volume of traffic
	55s)	1 5 d d (5 6 mpm).	
	333)	Intervention:	Further advice needed from KCC Highways as to
			appropriate intervention
		- Reduce speed limit up to the	
		Surrey border	
		 Consider a public footpath 	
8.	Stick Hill (B2026)	Speed and increase of traffic.	1.Traffic survey required to establish existing speeds and
			volume of traffic
		Intervention:	
		- Reduce speed limit from 50 to	Further advice needed from KCC Highways as to
		40 mph	appropriate intervention

Edenbridge Town Council - Highway Improvement Plan/Action Plan

9.	Main Road at Swan Lane Junction	P&T meeting 31.01.22 proposal for		
		yellow lines or other interventions to		
		restrict parking along Main Road		
		near the Swan Lane junction		